

Oil Field Environmental Incident Summary

Incident: 20140605162325

Date/Time of Notice: 06/05/2014 16:23

Responsible Party: Oasis Petroleum

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: NGUYEN FEDERAL 5693 44-27T

Field Name: ALGER

Well File #: 23527

Date Incident: 6/5/2014

Time Incident: 09:50

Facility ID Number:

County: MOUNTRAIL

Twp: 156

Rng: 93

Sec: 27

Qtr: SE SE

Location Description: 1/2 bll spill on location extending approximately 30 ft from well head.

Submitted By: Ryan Enget

Received By:

Contact Person: Ryan Enget
1001 FANNIN STE 1500
HOUSTON, TX 77002

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: Unknown

	Spilled	Units
Oil	25	Gallons

Recovered	Units
-----------	-------

Followup	Units
----------	-------

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

loss of well control

Areal Extent:

Potential Environmental Impacts:

low impact to surface water, oil sheen on location approx. 15 feet wide by 30 feet long

Action Taken or Planned:

pumping unit was shut down and ratigan closed. stuffing box rubbers were changed. notified Earthmovers to come and clean up the area of the spill. Change stuffing box rubbers before they are completely worn out

Wastes Disposal Location:**Agencies Involved:****Updates**

Date: 6/5/2014 **Status:** Reviewed - Assigned to Other Agency**Author:** O'Gorman, Brian**Updated Oil Volume:****Updated Salt Water Volume:****Updated Other Volume:****Updated Other Contaminant****Notes:**

Stuffing box release of 25 gallons of oil on constructed well pad. Surface water on well pad impacted. Followup with contact or NDIC necessary to determine if impacted surface water is removed or allowed to flow off site.